

Buckles are used as an alternative to steel strapping for securing special cargo and packages.

<b>HEBILL.13</b>	HEBILLAS METÁLICAS 13 mm. B4 (1000 uni.caja)
<b>HEBILL.16</b>	HEBILLAS METÁLICAS 16 mm. B5 (1000 uni.caja)
<b>HEBILL.19</b>	HEBILLAS METÁLICAS 19 mm. B6F (1000 uni.caja)
<b>HEBILL.25</b>	HEBILLAS METÁLICAS 25 mm. B8F (500 uni.caja)
<b>HEBILL.35</b>	HEBILLAS METÁLICAS 35 mm. B10F (250 uni.caja)
<b>HEBILL.50</b>	HEBILLAS METÁLICAS 50 mm. 5 Tn. (50 un.)
<b>HEBILL.9</b>	HEBILLAS METÁLICAS 9 mm. B3 (1000 uni.caja)
<b>HEBILL13F</b>	HEBILLAS MET.FOSFATADAS 13mm. B4F (1000 uni.caja)
<b>HEBILL16F</b>	HEBILLAS METÁLICAS 16 mm. B5F (1000 uni.caja)
<b>HEBILL35G</b>	HEBILLAS METÁLICAS 35 mm B10G (250 uds/caja)
<b>RH02L</b>	ANILLA Y PUENTE 38mm.D-10mm.
<b>RH030</b>	ANILLA Y PUENTE 30mm.D-6mm.

